

HEAVY DUTY MOTOR TUNING

X AND Y AXIS

STEPS PER INCH 979.415

VELOCITY 500

ACCELERATION 35

Z AXIS

STEPS PER INCH 10000

VELOCITY 100

ACCELERATION 35